

DUMPS ARENA

HCNP-DCF-Build Facility Development Optimization

Huawei H12-425

Version Demo

Total Demo Questions: 15

Total Premium Questions: 240

Buy Premium PDF

<https://dumpsarena.co>

sales@dumpsarena.co

sales@dumpsarena.co
dumpsarena.co

QUESTION NO: 1

On the Current Alarm page of NetEco, filter criteria can't set to search for the required alarms.

- A. TRUE
- B. FALSE

ANSWER: B

QUESTION NO: 2

After the UPS5000-E system is installed, which of the following items need to be checked?

- A. if UPS and battery system mechanical installation is firm and stable
- B. if the cable layout considers other system wiring in the future
- C. if the ground connection is reliable
- D. The positive and negative terminals of the battery are wired correctly.

ANSWER: A B C D

QUESTION NO: 3

Which air supply modes requires reasonable raised floor height?

- A. Air supply mode using blast caps
- B. Under floor air supply mode.
- C. Air supply mode using wind pipe
- D. In-row horizontal air supply mode

ANSWER: B

QUESTION NO: 4

Which are advantages of NetCol5000-A-2 kW?

- A. DC variable-frequency compressor is configured
- B. Constant frequency compressor is configured.
- C. In-row cooling
- D. EC fan is configured

ANSWER: A C D**QUESTION NO: 5**

Which is not included in the routine maintenance of the ECC800 module?

- A. Check whether the power indicator is normal
- B. Check the fans for the ECC800 module
- C. Check whether the power cable is properly connected
- D. Create a micro-module view

ANSWER: D**QUESTION NO: 6**

A maximum of () smart ETH gateways can be cascaded.

- A. 8
- B. 16
- C. 32
- D. 44

ANSWER: C

QUESTION NO: 7

On the NetEco, the door status is always open, we can identify with the faulty by ().

- A. Checking whether the door is closed.
- B. Checking whether cable are connected to the access actuator.
- C. Checking whether the angle and tightness of the door magnet are appropriate
- D. Checking the AC actuator cable

ANSWER: A B C**QUESTION NO: 8**

When connecting the refrigerant pipe, to prevent the pipe from being oxidized, it is necessary to introduce a small amount of nitrogen gas during welding.

- A. TRUE
- B. FALSE

ANSWER: A**QUESTION NO: 9**

Which component does not support wireless networking?

- A. Access actuator
- B. AC Actuator
- C. ETH converter
- D. XXX

ANSWER: C**QUESTION NO: 10**

Which of the following factors affect VRLA battery life?

- A. ambient emperature
- B. Number of cycles
- C. Depth of discharge
- D. ambient humidity

ANSWER: A B C D

QUESTION NO: 11

The compressor of NetCol5000-A generates a loud noise, possible reasons ().

- A. Liquid refrigerant is returning to the compressor.
- B. The lubricant is insufficient
- C. The sheet metal for securing the compressor during transportation are not
- D. The phase sequence of power supply may be incorrect

ANSWER: A B C

QUESTION NO: 12

If multiple data centers need to be monitored at the same time hierarchical deployment is available.

- A. TRUE
- B. FALSE

ANSWER: A

QUESTION NO: 13

The humidification of NetCol5000-A fails, the possible reasons ().

- A. The indoor temperature is low.
- B. The humidifier cylinder is damaged.
- C. The humidifier circuit breaker is disconnected.

D. The outdoor unit is not running

ANSWER: A B C

QUESTION NO: 14

The indoor fan does not work when the NetCol5000-A is started, the possible reason is that ().

- A. The air filter is dirty or blocked
- B. The power module of the fan is faulty or abnormal.
- C. The forcible drainage system is faulty
- D. The condensate drainpipe is blocked

ANSWER: B

QUESTION NO: 15

Draining impurities from the refrigerant pipe should

- A. Block one of the pipe ports.
- B. Fill the pipe with high-pressure nitrogen.
- C. Quickly remove the pipe plug and avoid facing people to prevent injury.
- D. To discharge nitrogen from the outdoor unit

ANSWER: A B C