

# DUMPS ARENA

**HCIA-Transmission V2.5**

**Huawei H31-311 V2.5**

**Version Demo**

**Total Demo Questions: 10**

**Total Premium Questions: 199**

**Buy Premium PDF**

**<https://dumpsarena.co>**

**[sales@dumpsarena.co](mailto:sales@dumpsarena.co)**

**sales@dumpsarena.co**  
**dumpsarena.co**

**QUESTION NO: 1**

Which of the following statements about the MST functional module is correct? (Multiple choice).

- A. MST is both the source and sink of MS. .
- B. MST implements BIP-8 statistical computation of B2 bytes.
- C. MST returns bit error messages, but does not return a specific number of bit errors
- D. MST provides an E20 orderwire channel. .

**ANSWER: A D**

**QUESTION NO: 2**

Which of the following logic function blocks are involved in processing clock signals? (Multiple choice).

- A. SPI
- B. RST
- C. MCF
- D. SETS

**ANSWER: A D**

**QUESTION NO: 3**

Only one TCM can be used at one site

- A. True
- B. False

**ANSWER: B**

**QUESTION NO: 4**

What are the basic features of the U2000? Multiple Choices

- A. Security management
- B. Topology management

- C. Alarm management
- D. Performance management

**ANSWER: A B C D**

#### QUESTION NO: 5

Which of the following different types of ESC are divided according to the principles of implementation? (Multiple choice)

- A. insert DCC
- B. Fixed frame structure DCC
- C. Pilot adjusts DCC
- D. None of the above

**ANSWER: B C**

#### QUESTION NO: 6

Which of the following statements about the clock source are incorrect?

- A. The internal clock source has the lowest priority due to low accuracy.
- B. Typically, a branch clock is not used as a clock source for a device.
- C. Select the same SSM co-editor for all NE in the clock protection subnet
- D. If the difficulty SSM protocol is enabled, you need to set the clock source ID to correct the answer.

**ANSWER: D**

#### QUESTION NO: 7

Which of the following is the frame indicated by the VC-4 J1 byte by the AU pointer of the current frame?

- A. Current framework
- B. Next frame
- C. Previous frame
- D. None of the above

**ANSWER: B**

**QUESTION NO: 8**

In the case of a 1+1 linear MSP, which of the following switching modes does not require the APS protection protocol full (multiple choice) to be enabled

- A. Single-ended reply mode (correct case management).
- B. Single-ended non-reply pattern
- C. Double-ended reply mode
- D. Double-ended non-reply mode

**ANSWER: A B****QUESTION NO: 9**

The refractive index  $n_1$  of the fiber core must be the Q of the cladding refractive  $n_2$ , which is a necessary condition for transmitting the optical signal in the optical fiber.

- A. is higher than
- B. Below
- C. Equal

**ANSWER: A****QUESTION NO: 10**

By default, B2-EXC alerts are reported when the number of B2 bit errors exceeds the ( ) threshold.

- A. 0.000000001
- B. 0.00001
- C. 0.001
- D. 0.01

**ANSWER: C**